

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	2817	DATE	September 14, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	①Improper structure for fixing the exhaust pipe between the engine and the catalytic muffler might cause a crack at welded part of the support stay on the exhaust pipe. Therefore, it might cause leakage of exhaust gas to outside and the exhaust sound also might be increased.		
	②Sealing performance at the exhaust pipe joint might be insufficient due to low tightening torque for clamping and/or dispersion of the parts accuracy. Therefore, exhaust gas leakage from the joint might happen and the disconnection of the joint might increase the exhaust sound.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT-SM221	FG09,FG15,FG18	2008 ~ 2011	577
EBT-SM225	FG20,FG25	2008 ~ 2011	235
EBT-SM226	FG30	2008 ~ 2011	22
EBT-M232	FG25	2009 ~ 2011	3
EBT-M255	FG30	2008 ~ 2011	4
EBT-M225	FG20,FG25	2008 ~ 2010	3
EBT-M226	FG30,FG35A	2008 ~ 2011	10
EBT-M227	FG25H	2009 ~ 2010	2
		TOTAL	856