

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-1775	DATE	Sep. 15, 2011
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>2010 Explorer and Sport Trac, – Manual Seat Recliner Replacement</p> <p>Certain 2010 Explorer, and Sport Trac vehicles equipped with front manual seat recliners may not maintain locked position during vehicle impact due to on some recliner gear plate, the teeth were out of specification resulting in limited pawl to gear plate engagement and cam rotation.</p> <p>There have been no known accidents, injuries, or fires attributed to this condition.</p> <p>This repair will involve replacement of the manual recliner mechanisms. This will be accomplished by replacing the inboard and outboard recliner mechanism.</p> <p>Note: In order to replace the components above, the seats must be removed from the vehicle and partially disassembled. Some of the disassembled parts are not reusable. Therefore, kits will be released that include all parts necessary for the repair.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-1FMEU74P	Ford Explorer	2010	67 units
ABA-1FMWU74P	Ford Explorer	2010	15 units
ABF-1FMKU51	Ford Explorer Sport Trac	2010	6 units
TOTAL			88 units