VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2819	DATE	Sep. 20. 2011		
MANUFACTURER	YAMAHA MOTOR CO., LTD	D.			
DESCRIPTION OF DEFECT	As for the oil pump for the motor, due to its inappropriate structure, the housing section of the said pump may become worn. For this reason, the continuous use of the oil pump may cause the pir which is to activate the rotor of the said pump to come off during the progression of wear of the housing section so that the engine may not have enough oil supplied. In the worst-case scenario, running may become impossible.				

	COMMERCIAL MODEL		NUMBER OF	
TYPE	NAME	YEAR RECALLED		VEHICLE
EBL-RP22J	VMAX	2009~2010		7 2 1
			TOTAL	7 2 1