

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2823	DATE	September 20 . 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>Terminals of inner electronic devices in controller for motors on electric forklift might be damaged due to improper material of inner parts, or improper manufacturing process.</p> <p>Therefore a controller might loose normal control, and a vehicle might not travel, steering wheel might not move, or a vehicle might travel in spite of neutral position.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-SM236	FB09H,FB10,FB14 FB15,FB15HB	2006 ~ 2011	933
ZAF-SM237	FB18,FB18HB FB20A,FB20AHB	2007 ~ 2011	214
ZAF-SM243	FB15G,FB18G,FB20AG	2007 ~ 2010	9
ZAF-M238	FB09ML,FB10ML,FB13ML	2006 ~ 2011	51
ZAF-M239	FB15ML	2007 ~ 2011	81
ZAF-M237	FB20A	2007	1
ZAF-SM236K	FB09H,FB10,FB14 FB15,FB15HB	2011	18
ZAF-SM237K	FB18,FB20A,FB20AHB	2011	3
ZAF-M239K	FB15ML	2011	1
		TOTAL	1311