

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2825	DATE	September 21, 2011
MANUFACTURE	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On certain service parts of front wheel hub, the positions of hub bolt holes were out of spec due to inappropriate manufacturing process. If wheel hub is replaced with this part, the wheel hub and the hub bolts may interfere with disc plate. If the customer continuously uses under this condition, lug nuts may be loosened and/or hub bolts may be broken. In the worst case, vehicle cannot be moved.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KD-LVLR	Mazda MPV	1998	1
KD-SGLR	Mazda BONGO FRIENDEE	1996-1997	3
		Total	4