

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2831	DATE	September—27—2011
MANUFACTURER	TOKYU CAR SPV CORPORATION		
DESCRIPTION OF DEFECT	<p>In the production of the tractor for the flat floor semitrailer pulling with the inclination carrier, because the strength of the steel-made connection of the hydraulic system is insufficient for the vibration when running, there is a possibility that the crack occurs when keeping using it under such a condition.</p> <p>A fire might occur when the crack of connection is caused, the hydraulic fluid leaks, and it drops it to the vehicle exhaust emission purifier on the tractor side.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL—EXY52J3W	GIGA	2005	1
PJ—EXY52J6	GIGA	2005~2007	19
PKG—EXY52J8	GIGA	2007~2009	135
LKG—EXY52AJ	GIGA	2011	1
ADG—GW4XLG	QUON	2007~2009	13
PJ—FV50JHR	SUPER GREAT	2007~2008	3
BKG—FV50JJR	SUPER GREAT	2008~2009	5
BDG—SS1EKXA	PROFIA	2008	1
			TOTAL 178