

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2835	DATE	Oct. 20, 2011
MANUFACTURER	SUBARU TECNICA INTERNATIONAL INC.		
DESCRIPTION OF DEFECT	Due to the inappropriate design of the air intake duct, the metal connector part of the air intake duct can come into contact and rub against the fuel line. This could cause a pinhole to appear on the fuel line, which might lead to a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CH-GDB	IMPREZA S203	2005	552
CH-GDB	IMPREZA S204	2006	510
CH-GDB	IMPREZA TYPE RA-R	2007	300
		TOTAL	1,362