

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2841	DATE	October 21 , 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to improper release point on the clutch pedal of forklift truck, the shift position might be changed without fully disengaging the clutch, and inner parts of transmission might wear. Therefore, if a machine is continuously used under the above condition, inner parts of a transmission might be damaged, and a vehicle might not travel in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SM220	FG10,FG14,FG15,FG18	2008	11
EBT-SM221	FG09,FG15,FG18	2008~2011	227
EBT-SM221K	FG09,FG15,FG18	2011	17
M224	—	2004~2008	1019
SM225	—	2004~2008	400
EBT-SM225	FG20,FG25	2008~2011	81
EBT-SM225K	FG20,FG25	2011	11
SM226	FG30	2007~2008	2
EBT-SM226	FG30	2008~2011	8
M225	—	2005	1
EBT-M225	FG20	2010	1
M226	—	2005~2006	2
SA-M222	—	2004~2008	105
SA-SM223	FD10,FD15	2008	2
EDM-SM223	FD10,FD15,FD18	2008~2011	90
EDM-SM223K	FD15,FD18	2011	6
SB-SM228	—	2004~2009	523
EDM-SM228	FD20,FD25	2010~2011	103
EDM-SM228K	FD20,FD25	2011	33
SB-SM229	—	2004~2009	86
EDM-SM229	FD30	2009~2011	25
EDM-SM229K	FD30	2011	1
SB-M228	—	2005~2009	18
EDM-M228	FD20	2009	1
SB-M229	—	2005~2009	10
EDM-M229	FD30	2010~2011	2
SB-M230	—	2005~2007	5
SB-M231	—	2005~2008	29
		TOTAL	2819