

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 8 4 0	DATE	O c t . 2 5 . 2 0 1 1
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the fuel device, due to an inappropriate molding of the fuel hose that connects the fuel injection device, adherence of the connecting section of the said hose may be insufficient. Therefore, during continuous use, because of the pressure of the fuel that was generated during the use process, the airtightness of the said connecting section may be impaired and the fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
E B L - V H 0 2 J	XVS400 DRAGSTAR	2 0 0 9 ~ 2 0 1 1	7 6 0
	XVS400C DRAGSTAR CLASSIC	2 0 0 9 ~ 2 0 1 1	1, 1 6 8
		TOTAL	1, 9 2 8