

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2846	DATE	November 4 ,2011
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the Compressed Natural Gas (CNG)-fueled L/D vehicles, it has been found that the tightening torque of bolts in the fastening structure of the fuel tank bracket was insufficient, thereby causing the bolts to loosen. If they are used as are, the bolts will come off. If it occurs, there is a possibility that, in the worst case, the fuel tank comes off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
AFG-NKR82AN AFG-NKR82N NFG-NKR82AN NFG-NKR82N	ELF	2005-2007	1,326
AFG-NPR82AN AFG-NPR82N NFG-NPR82AN		2005-2007	1,188
AFG-AKR82AN AFG-AKR82N	ATLAS	2005-2007	32
AFG-APR82AN		2006	1
AFG-BKR82AN AFG-BKR82N	CONDOR	2005-2007	26
AFG-BPR82AN AFG-BPR82N		2005-2006	9
AFG-LKR82AN AFG-LKR82N	TITAN	2005-2007	17
AFG-LPR82AN AFG-LPR82N		2005-2006	3
		TOTAL	2,602