## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2847	DATE	November 4,2011
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the hybrid L/D trucks, it has been found that, in the wake of an inadequate fastening structure of the hybrid motor bracket, there occurred a clearance between the frame cross-member and the bracket. Thus, excessive stress is produced in the motor bracket fixing bolts from input, etc., received during running. If they are used as are, the bolts will be broken. If it occurs, there is a possibility that, in the worst case, the motor comes off.	

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
BJG-NJR85AN	ELF	2007-2010	324
VD-NKR81AN	7 6	2005-2007	234
BJG-NLR85AN		2007-2009	12
BJG-NMR85AN		2007-2010	168
VD-NPR81AN		2005-2007	147
BJG-NPR85AN	7 6	2007-2010	125
BJG-AJR85AN	ATLAS	2010	1
BJG-AMR85AN		2008-2009	4
BJG-APR85AN	7 6	2008-2009	6
		TOTAL	1,021