

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 8 5 2	DATE	Nov.10.2011
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Due to the inappropriate electric wiring in an inspection facility of the engine manufacturing plant, an element of the air-fuel ratio sensor might be damaged during the inspection process. The air-fuel ratio sensor of the exhaust emission control system may be damaged on certain vehicles. As a result, the carbon monoxide emission may exceed the regulatory value.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	
CBF-VRE25	N I S S A N C A R A V A N	2 0 1 0 ~ 2 0 1 1	1, 5 8 5	
CBF-CSGE25			2 6 8	
CBA-SGE25			5 2 7	
CBF-DSGE25			6 1 7	
CBF-SQ2F24	N I S S A N A T L A S		5 1 6	
CBF-SQ1F24			9 5	
CBF-JVRE25	I S U Z U C O M O			2 7
CBF-JCSGE25				5
CBF-JDSGE25		2		
CBF-ASQ2F24	I S U Z U E L F			7
CBF-ASQ1F24			1	
			TOTAL	3, 6 5 0