

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-1793	DATE	Nov 17, 2011
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	The rear brake light switch installed on these vehicles may be exposed to temperatures that can degrade its performance under certain riding conditions. This condition may affect brake lamp function and/or cause a brake fluid leak at the brake light switch affecting rear brake performance, possibly leading to a crash and potential injury or death.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
FB4	FLHR	2008-2011	794
FBM	FLHR103		71
FC4	FLHTCU		1005
FCM	FLHTCU103		328
KB4	FLHX		2135
KBM	FLHX103		99
KH4	FLTRX		598
KHM	FLTRX		47
FF4	FLHTC		919
FR4	FLHRC		349
FS4	FLTR		201
FV4	FLHT		110
FG4	FLHTCU S/C		83
PV4	FLTR3-CVO		119
KEM	FLHTK103		376
KGM	FLTRU103		210
KMM	FLHTK W/SC		19
TA8	FLTRUSE		121
PZ8	FLHXSE/FLHXSE2		462
PR4	FLHTCU4-CVO		201
PR8	FLHTCUSE5/FLHTCUSE6/ FLHTCUSE7	476	
		TOTAL	8723