

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2857	DATE	November. 24. 2011
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to improper welding of the side frame and front lower cross member, the weld area strength is insufficient. Therefore, if the vehicle continues to be driven in this condition, the weld area is separated due to vibration while driving etc., causing dislocation of the front lower cross member. In the worst case, the rear end of the lower arm, to which front wheels are mounted, comes off, and the vehicle may become undrivable.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GD-HA6	ACTY	2002	43
		2002	2
GD-HA7		2001~2002	123
		2002	6
GD-HH5		2002	4
GD-HH6		2002	7
LA-HM1	VAMOS	2001	86
		2001~2002	86
LA-HM2		2001~2002	22
		2001~2002	42
		TOTAL	421