

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2861	DATE	December 1, 2011
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>At accelerator cable assembling process, short inner sleeves (resin tubes) were mistakenly installed on some of accelerator cables.</p> <p>Even if the cable with shorter tube continuously used on the vehicle as it is, inner cable may be damaged. In worst case, the vehicle may become hard to drive, as the engine R.P.M. will not be increased when depressing the accelerator pedal.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-DA64V	EVERY	2011	125
GBD-DA64V			1
ABA-DA64W			47
EBD-DG64V	SCRUM		45
ABA-DG64W			16
			TOTAL