

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1804	DATE	December 2, 2011
MANUFACTURER	HONDA OF AMERICA MFG.,INC.		
DESCRIPTION OF DEFECT	Due to an inappropriate gas generating propellant inside the inflator of the driver's SRS airbag, if an affected airbag deploys, internal pressure abnormally increases and causes the inflator canister to rupture. Therefore, the components tear through the airbag cushion material causing injury to vehicle occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-UA4	INSPIRE SABER	2001	3
		2001~2002	735
		2002	38
LA-UA5		2001~2002	571
		2002	14
		TOTAL	1,361