

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1805	DATE	December 2, 2011
MANUFACTURER	HONDA CANADA INC.		
DESCRIPTION OF DEFECT	Due to an inappropriate gas generating propellant inside the inflator of the driver's SRS airbag, if an affected airbag deploys, internal pressure abnormally increases and causes the inflator canister to rupture. Therefore, the components tear through the airbag cushion material causing injury to vehicle occupants.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-RL1	LAGREAT	2001	2
		2001~2002	528
		TOTAL	530