

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1806	DATE	December 2, 2011
MANUFACTURER	HONDA OF AMERICA MFG.,INC.		
DESCRIPTION OF DEFECT	In the braking device equipped with the front wheel and rear wheel interlocking brake system (Dual Combined Brake System), the structure of the second master cylinder, which transfers the brake force from the front wheel to the rear wheel during braking, is inappropriate. Due to this, the hydraulic path for releasing hydraulic pressure is clogged. Therefore, the rear brake remains effective, and in the worst case, overheating may occur in the area around the brake, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BC-SC47	GOLD WING	2001	570
		2002~2003	650
		2004	50
		2005	80
EBL-SC47		2006	444
		2007	313
		2008	242
		2009	151
		TOTAL	2,500