

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2864	DATE	December 7, 2011
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>As material of rubber hose connected to the gauge pressure adjusting valve for fuel tank was not proper, internal valve of the gauge pressure adjusting valve may be swollen by plasticizer coming out from the rubber hose, and gauge pressure of fuel tank may not be adjusted.</p> <p>Then, the vehicle may not be restarted if engine stalled, as gauge pressure of fuel tank will be down and the fuel tank will be deformed to have damage on the fuel pump.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LA-TA02W	ESCUDO	2000	378
LA-TA52W		2000~2002	573
LA-TL52W		2000~2005	14,710
LA-TD62W		2000~2003	1,481
LA-TX92W	GRAND ESCUDO	2000~2003	4,962
UA-TX92W		2003~2005	1,504
		TOTAL	23,608