

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2865	DATE	December · 9 · 2011
MANUFACTURER	SOHSHIN CO., LTD.		
DESCRIPTION OF DEFECT	Owing to insufficient production of the steering shaft part that holds the steering to the shaft, the installation angle of this part to the shaft is not correct and interferes with the steering shaft joint section, which causes steering operation impossible when tilted the steering toward driver side.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PY5KUFM	—	PY5KUFM-0011~PY5KUFM-0024 Apr. 1 2003 ~ Mar. 31 2011	14
PY5KUGM	—	PY5KUG-0001~PY5KUG-0003 Apr. 1 2003 ~ Mar. 31 2011	3
			TOTAL
			17