

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-1807	DATE	December 13, 2011
MANUFACTURE	Triumph Motorcycles Limited (Japanese Importer : Triumph Japan K.K. )		
DESCRIPTION OF DEFECT	EVAP system connector which is not used for Japan specification model is not fixed correctly. This connector or cable may touch exhaust pipe. The connector or cable may be melted by heated exhaust pipe, and naked positive cable may touch to the exhaust pipe. This makes electric short and Engine Management System fuse blow. Then engine stall happens finally.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SMTTMD106	Daytona 675	2011-2012	102
LE2	Daytona 675R	2011-2012	78
		TOTAL	180