

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2869	DATE	20 December 2011
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO, LTD.		
DESCRIPTION OF DEFECT	The electric wiring which is covering by protection tube under the operator's frame. The water is gathered in the protection tube, and then the water will in the electric connector which is used for forward and reverse signal. Therefore there is possibility that the vehicle will not be able to travel, because of the safety system will work.		
	There is the case that the electrical wiring which is passed top of the transmission closes the transmission housing. Therefore, the electrical wiring is damaged by the vehicle vibration. So that there is possibility the electric wire will be damaged and the fuse will be burned, and then the parking brake will apply.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARKS
KDP - S59 KDP - S59F	ZW100	2010-2011	92	:92 :92
KDP - S60 KDP - S60F	ZW120	2010	14	:14 :14
KDP - HS59 KDP - HS59L	ZW100	2010-2011	157	:137 :157
KDP - HS60 KDP - HS60L	ZW120	2010-2011	16	:11 :16
		TOTAL	279	:254 :279