

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 8 7 0	DATE	December.20.2011
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	It revealed that there are some inappropriate pipe arrangements in the middle part of the power-steering hydraulic piping system where the hose is fixed. Thus, the continuous use of the system may induce the damage in the hose and would possibly result in the hose damage and eventually leads to too much enhanced steering wheel operational ability due to the oil leakage from the power-steering.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CD5XL	—	2010~2011	3
LDG-CD5XM	—	2010~2011	12
LKG-CD5YA LDG-CD5YA	—	2010~2011	54
LDG-CD5YL LKG-CD5YL	—	2010~2011	107
LDG-CD5ZA LKG-CD5ZA	—	2010~2011	970
LDG-CD5ZE LKG-CD5ZE	—	2010~2011	66
LDG-CD5ZL LKG-CD5ZL	—	2010~2011	108
LDG-CF5XL	—	2010~2011	61
LDG-CG5YA LKG-CG5YA	—	2010~2011	14
LKG-CG5YE	—	2010	1
LDG-CG5YL	—	2011	1
LDG-CG5ZA LKG-CG5ZA	—	2010~2011	976
LDG-CG5ZE LKG-CG5ZE	—	2010~2011	119
LDG-CG5ZL LKG-CG5ZL	—	2010~2011	52
LKG-CG5ZM	—	2010~2011	11

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDG-CK5XL	—	2010~2011	17
LDG-CV5XA	—	2010~2011	34
LDG-CV5XL	—	2010~2011	17
LDG-CV5YB LKG-CV5YB	—	2010~2011	16
LDG-CV5YL	—	2010~2011	81
LDG-CW5XL LKG-CW5XL	—	2010~2011	327
LDG-CW5YL LKG-CW5YL	—	2010~2011	247
LDG-CW5ZA LKG-CW5ZA	—	2010~2011	56
LDG-CW5ZL LKG-CW5ZL	—	2010~2011	152
LDG-CX5YA LKG-CX5YA	—	2010~2011	33
LDG-CX5YL	—	2010~2011	12
LDG-CZ5YL	—	2010~2011	154
LKG-GK5XAB LKG-GK5XAD LKG-GK5XAE LKG-GK5XAK	—	2010~2011	722
LDG-GK6XAB LKG-GK6XAB LKG-GK6XAD LKG-GK6XAE	—	2010~2011	440
LDG-HF5XL	—	2010	8
LDG-HZ5YL	—	2010	6
LDG-SF5XL	—	2010	5
LDG-SZ5YL	—	2010~2011	20
		TOTAL	4,902