

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2872	DATE	December 26, 2011
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Due to improper processing of the snap ring groove on the driving piston, which is installed in the hydraulic pump of transmission, the snap ring might be fractured. Therefore, the driving piston can't be changed when the change lever is operated from backward to neutral, and a machine might reverse.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-WA106	WA30-6	2008~2011	36
EDM-WA106K	WA30-6	2011	1
EDM-WA106A	WA30-6	2008~2011	999
EDM-WA106AK	WA30-6	2011	97
EDM-WA107	WA40-6,WA50-6	2008~2011	133
EDM-WA107K	WA40-6,WA50-6	2011	11
EDM-WA107A	WA40-6,WA50-6	2008~2011	1,268
EDM-WA107AK	WA40-6,WA50-6	2011	148
		TOTAL	2,693