VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2873	DATE	December 26, 2011		
MANUFACTURER	Komatsu Ltd.				
DESCRIPTION OF DEFECT	Due to improper installation of clutch pressure sensor, which installed in the transmission, the pin which is sensor's inner part might be damaged. Then electricity doesn't supply normally. Therefore, clutch pressure cannot be detected and in the worst case a machine might not travel in a specific speed range.				

TYPE	COMMERCIAL NAME	3	IODEL YEAR CALLED	NUMBER OF VEHICLE
HV3000	HV3000-1	2004~2008		7
HV6000	HV6000-1	2004~2008		2 4
			TOTAL	3 1