

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2874	DATE	December 27.2011
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	The control program of power transmitting device may send wrong signal of driving speed because the control program does not function properly when operating forward and reverse drive switch lever. The machines equipped with the program may run in the opposite direction of the forward and reverse drive switch lever position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-34L	EG326Y	2011	8
	EG328Y	2011	10
	EG330Y	2011	15
	EG334Y	2011	30
EDM-45L	EG437Y	2009~2011	23
	EG441Y	2009~2011	39
	EG445Y	2009~2011	61
KDN-53L	EG453Y	2010~2011	71
TOTAL			257