

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	2876	DATE	December 27, 2011
MANUFACTURER	NITTSU SHOJI CO., LTD. Tsukiji 5 - 6 - 10, Chuo - ku, Tokyo, 104 - 8406 Japan		
DESCRIPTION OF DEFECT	Because the management of the caulking tool for the drain cook pin of the air brake tank was inappropriate, the fixation of O ring of that pin became insufficient. On that account, at the operation of drainage, some O rings come off and air leaks from that pin and then parking brake works. In this condition, as the result, the brake equipments will be overheated and lead to a fire in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
NT2910	-	2011	2
		TOTAL	2