VEHICLE SAFETY / POLLUTION RECALL CAMPAINGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1811	DATE	Jan 25, 2012	
MANUFACTURE	General Motors Company			
	(Japanese Importer : General Motors Japoan Ltd.)			
DESCRIPTION OF DEFECT	These vehicles may have a transmission shift cable that was improperly installed and may come out of the transmission bracket. This could prevent the driver from shifting the transmission in or out of gear, resulting in no motion or unexpected vehicle motion. If this condition were to occur, the PRNDL position indicator in the instrument panel would be correct but the console shifter may not display the correct gear position and the driver may not be able to restart the vehicle or shift the vehicle into PARK. This could allow the vehicle to roll away if the driver has exited the vehicle without applying the park brake and cause a possible crash without prior warning.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-T166C	SRX	2010 - 2011	111
		TOTAL	111