

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2882	DATE	Jan.26.2012
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain medium and light duty buses, due to inadequate wiring for failure warning that is related to an electric power supply to ABS (Anti Lock Brake System) , when failure arises in the wiring that is related to an electric power supply to ABS, the ABS warning lamp may not be lighted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-HX9JHBE	HINO Poncho	2011	4
SDG-HX9JLBE		2011	23
SKG-HX9JLBE			
SDG-RR7JJCA	HINO Melpha	2011	18
		TOTAL	45