

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2883	DATE	January 26 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain medium duty buses, due to inadequate wiring for failure warning that is related to an electric power supply to ABS (Anti Lock Brake System) , when failure arises in the wiring that is related to an electric power supply to ABS, the ABS warning lamp may not be lighted.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SDG-RR7JJCJ	ISUZU GALA MIO	2011	14
		TOTAL	14