

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	2889	DATE	January 26 ,2012
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		In the M/D route buses' rear door, a door wiring installation position is inadequate, so the door engine rod or the door bracket rubs against the door wiring. Thus, if it is used as is, the wiring will be disconnected. If it occurs, there is a possibility that in the worst case, the door may not be opened and closed, thereby rendering the vehicles inoperative.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-LR233J1	ERGA MIO	1999-2004	331
TOTAL			331