VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2892	DATE	February.02, 2012
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to inadequate internal structure of the brake switch, when brake is operated, spring which closes the contact points is electrically energized and heated, and may over stretch the spring. If motorcycle is continuously used in this condition, spring tension is reduced and contact points pressure will become insufficient and cause contact malfunction. This will lead to brake light failure and in the worst case engine can not be started.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JBK-CJ45A	SKYWAVE	2011	451
JBK-CJ46A	SKYWAVE	2011	2383
		TOTAL	2834