

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 8 9 4	DATE	February 20 , 2012
MANUFACTURER	NIPPON YUSOKI C O .,LTD.		
DESCRIPTION OF DEFECT	<p>In the controller to control the traction motor and the hydraulic motor of the electric forklift trucks, due to an improper material of the parts (Lead-bar), an electrolytic corrosion will be caused, and loosen the locknut at Lead-bar.</p> <p>Therefore, when the truck keeps going, the conductivity of Lead-bar would be damaged by overheat.</p> <p>The truck would be unable to drive in the worst case.</p>		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
NICHIYU 241AC	T R A N S E R	2 0 1 1	2 9
NICHIYU 251AC		2 0 1 1	1
TOTAL			3 0