

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|--|---------------------|-------------------|
| CAMPAIGN No. | 2905 | DATE | March, 02, 2012 |
| MANUFACTURER | KUBOTA Corporation | | |
| DESCRIPTION OF DEFECT | <p>① The pressure plate of turning clutch is not durable enough. It may be broken after certain hours operation. That leads to deteriorate of the turning performance.</p> <p>② The clamp of the injection pipe is not suitable enough. When work is frequently done at the certain engine rpm, excessive stress occurs on the injection pipe. It leads to crack and fuel leak problems.</p> | | |
| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
| KDN-C425 | ER467 | 2008~2011 | 963 |
| | ER456 | 2008~2011 | 883 |
| | | TOTAL | 1,846 |