

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai 1820	DATE	March 2, 2012
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	If a headlight module is not locked correctly, relative movements with respect to the wing will occur whilst driving and can cause the headlight to become detached from the wing in rare cases.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-92AM5502	Cayenne	2011 and 2012	830
ABA-92AM5502A	Cayenne	2011 and 2012	73
ABA-92AM48	Cayenne S	2011 and 2012	268
ABA-92AM48A		2011 and 2012	54
	Cayenne Turbo	2011 and 2012	304
DAA-92ACGE	Cayenne S Hybrid	2011 and 2012	267
DAA-92ACGEA	Cayenne S Hybrid	2011 and 2012	105
TOTAL			1901