

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2909	DATE	March 14, 2012
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	Cables for directional and speed change used on manual shift transmission of forklift trucks may be bent and damaged during assembly. Therefore, if a machine is continuously used under the above condition, the cable might be cut, and a machine might not travel in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SM220	FG10,FG14,FG15,FG18	2008	11
EBT-SM221	FG09,FG15,FG18	2008~2011	227
EBT-SM221K	FG09,FG15,FG18	2011	37
M224	—	2004~2008	1019
SM225	—	2004~2008	400
EBT-SM225	FG20,FG25	2008~2011	81
EBT-SM225K	FG20,FG25	2011	20
SM226	FG30	2007~2008	2
EBT-SM226	FG30	2008~2011	8
EBT-SM226K	FG30	2011	1
M225	—	2005	1
EBT-M225	FG20	2010	1
M226	—	2005~2006	2
SA-M222	—	2004~2008	105
SA-SM223	FD10,FD15	2008	2
EDM-SM223	FD10,FD15,FD18	2008~2011	90
EDM-SM223K	FD10,FD15,FD18	2011	18
SB-SM228	—	2004~2009	523
EDM-SM228	FD20,FD25	2010~2011	103
EDM-SM228K	FD20,FD25	2011	65
SB-SM229	—	2004~2009	86
EDM-SM229	FD30	2009~2011	25
EDM-SM229K	FD30	2011	22
SB-M228	—	2005~2009	18
EDM-M228	FD20	2009	1
SB-M229	—	2005~2009	10
EDM-M229	FD30	2010~2011	2
SB-M230	—	2005~2007	5
SB-M231	—	2005~2008	29
TOTAL			2914