

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 9 1 1	DATE	M a r . 1 5 . 2 0 1 2
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the headlight, due to inappropriate specifications of the socket cover which was attached to the socket cord, when the headlight is turned on, the temperature inside the said cover becomes high and the pre-insulation of the electric wiring may melt. Therefore, during continuous use, because of a short circuit occurring in the electric wiring, the fuse may blow out and the safety lights, such as a headlight, may not turn on and at the same time, the horn also may not turn on.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAD-SY06J	EC-03	2010~2012	2,481
		TOTAL	2,481