

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|------------------------------|--|-------------|----------------|
| CAMPAIGN No. | 2912 | DATE | March 15, 2012 |
| MANUFACTURER | SUZUKI MOTOR CORPORATION | | |
| DESCRIPTION OF DEFECT | As clamp screw on fuel filler hose connected onto fuel tank was incorrectly tightened, the fuel hose may have a crack near the clamp. If the vehicle is continuously used as it is, there is a possibility to have a fuel leakage due to the crack will be expanded. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-----------------|---------------------|-------------------|
| DBA-ZC72S | SWIFT | 2010 ~ 2012 | 40,072 |
| DBA-ZD72S | | 2010 ~ 2012 | 5,682 |
| | | TOTAL | 45,754 |