

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai 1823	DATE	April 6, 2012
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the rapid-action coupling on a fuel line on the underside of the vehicle is touching a heating pipe. If the fuel line is touching, this can impair the locking function of the rapid-action coupling, causing the rapid-action coupling to open and as a result, fuel can leak out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-991MA104	911 Carrera	2013	17
ABA-991MA103	911 Carrera S	2013	53
		TOTAL	70