

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2919	DATE	Apr.11.2012
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the subject vehicles, due to insufficient strength of the attaching bolts for the connecting rods in the engine, there is a possibility that a bolt may fracture under the influence of the agent in the deteriorated engine oil. In this condition, the engine may be damaged, causing the vehicle to become inoperative and, in the worst case, resulting in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GF-SV50 GF-SV50G	VISTA	1998-2001	35,980
E-ST210 GF-ST210	CORONA	1996-2001	21,496
GF-SXN10	NADIA	1998-2001	12,934
		TOTAL	70,410