

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1839	DATE	April 23 rd 2012
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH+Co.KG (Japanese Importer: Nicole Racing Japan Co.,Ltd)		
DESCRIPTION OF DEFECT	Due to an inappropriate manufacturing process of the housing of electric additional coolant pump for turbocharger, a crack may occur on the housing. In such case, coolant or humid can enter from the crack, which might cause short circuit on the circuit board and scorch damage of plug connection might occur. In worst case, vehicle fire may occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-AM10	B5 Biturbo	2011	4
		TOTAL	4