

# VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 9 3 9	DATE	May 25, 2012
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>The engine room might have inadequacy of waterproof property, therefore, The engine pulley transfers for driving the alternator through the V-belt which may occur slip, if in the rain condition.</p> <p>Hence the V-belt become break-off with abnormal noise due to wear, if continue using in the same condition.</p> <p>Besides, electricity can not be charge as alternator improper driving, also the engine will be stop, and can not re-start at the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDP-WA115	WA100-6	2010-2012	787
KDP-WA115	WA150-6	2009-2012	168
KDP-WR004	WR12-6	2010-2012	5
		TOTAL	960