VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

	-	-		
CAMPAIGN No.	2942	DATE	MAY. 30. 2012	
MANUFACTURER	HANTA MACHINERY CO. LTD.			
DESCRIPTION OF DEFECT	The tail lamp will get a little dark when operating head lamp and direction indicator at the same time and then decreasing an electric current value of tail lamp, because an electric wiring is improper for lighting system.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM- F40WD3	F 4 0 WD 3	2 0 0 8 ~ 2 0 1 1	113
		TOTAL	1 1 3