VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2934	DATE	May, 31, 2012
	2001		may, 01, 2012
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	The rivet which fix the diaphragm spring on the pressure plate of the clutch might be abnormal heat treated. It may be broken off and that will lead to malfunction of disengagement of the clutch.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-KT1A	KT215	2012	75
	KT235	2012	34
	T245D	2012	314
	KT255	2012	49
EDM-KT1B	T265D	2012	203
	KT285	2012	43
	KT305	2012	17
		TOTAL	735