

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2949	DATE	June 6, 2012
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	<p>In engine crankshaft angle sensor on vehicle with turbo charging system, the coil wire may break from excessive vibration when repeatedly driving at high speed just after starting engine.</p> <p>Therefore, engine may stop while driving or may not start up.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-L405S	SONICA	2006-2009	21,819
CBA-L415S			3,627
CBA-L175S	MOVE	2006-2010	40,575
CBA-L185S			9,577
CBA-L275S	MIRA	2006-2010	4,076
CBA-L285S			953
CBA-L375S	TANTO	2007-2010	40,992
CBA-L385S			9,078
CBA-L575S	MOVE CONTE	2008-2009	6,257
CBA-L585S			1,486
		TOTAL	138,440