

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2946	DATE	June. 7, 2012
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	<p>Since certain affected Subaru vehicles may have been produced with the engine water pump having an inadequate assembling clearance at the bearing, it may be broken and the water pump will malfunction.</p> <p>Under these circumstances, the timing belt will be damaged and if the vehicle was continuously driven, engine will stall and will possibly lead to no restart condition.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-YA5	EXIGA	2008	4,655
DBA-YA4			3,279
DBA-YA5			3,916
DBA-GH2	IMPREZA	2008	4,907
DBA-GH3			1,730
CBA-GH8			604
CBA-GRB			658
DBA-GE2			266
DBA-GE3			68
CBA-SH5			FORESTER
DBA-SH5	4,231		
CBA-BL5	LEGACY	2008	745
DBA-BL9			168
CBA-BP5			1,588
CBA-BPH			598
DBA-BP9			172
		TOTAL	29,253