

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2955	DATE	June 19.2012
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	At steering system, welding on the side clutch fork link, which operate side clutch inside of the transmission, is insufficient. Accordingly, usage under such state will cause breakage on the link of the side clutch fork and disable the clutch from disengaging. In the worst case, it may make steering difficult.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C21K	AJ216	2009	81
	AJ218	2009	37
	AJ318	2009	22
TOTAL			140