

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import~~ Vehicles

CAMPAIGN No.	Gai-1853	DATE	June 27 <sup>th</sup> 2012
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to insufficient intensity of material, the connection line connecting right and left ventilation line at crank ventilation may get damaged. In such case, warning lamp lights on, rough idling might occur, and in worst case the engine might stall.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-GY44	BMW X5 M	2009 - 2011	60
ABA-GZ44	BMW X6 M	2009 - 2011	71
		TOTAL	131