

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2961	DATE	June 27 2012
MANUFACTURER	KATO WORKS CO.,LTD.		
DESCRIPTION OF DEFECT	It was found that guiding hole of the pushing pin for the valve-solenoid fitted to the transmission has been machined insufficiently, therefore, it might cause an error operation of the vehicles, that is, it might move forward direction even when you select the shift position to either reverse or neutral immediately after selecting forward driving position while warming up the vehicles in cold climate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KR353	KR-35H	1999~2001	2
KR511	KR-50H	2002	1
SD-KR512	KR-50H	2007~2008	21
SC-KR130	KRM-13H(M)	2005~2008	48
SD-KR248	KRM-25H	2008	8
SD-KRC001	KR-20H	2007~2008	7
SD-KRC002	KR-65H	2006	1
SD-KRC003	KRM-35H	2008	8
JDS-KRC005	KR-25H	2006~2012	570
JDS-KRC007	KRM-25H	2008~2012	38
JDS-KRC010	KRM-35H	2009~2012	51
TOTAL			755