

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|--------------|
| CAMPAIGN No. | 2 9 6 8 | DATE | July.12.2012 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | Due to inappropriate control process of the welding equipment, incomplete penetration might occur at the weld zone of some seatback strikers. The strength of weld zone may be insufficient on some rear seatback strikers which hold the rear seatback. If the seatback striker receives excessive input force in a frontal crash, it may be deformed. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|----------|-----------------|---------------------|--------------------|
| DBA-YF15 | J U K E | 2 0 1 2 | 13,748 |
| CBA-NF15 | | | 646 |
| CBA-F15 | | | 237 |
| | | TOTAL | 14,631 |